

Product Safety Recall

RUBBER TIE DOWN STRAPS

Sold at automotive and hardware stores Australia-wide between August 2008 and August 2011.

Identification: Black Rubber Tie Down Straps with distinctive hooks as depicted in the photo, in sizes 10", 15", 21" and 31", with product numbers 74-010, 74-0150, 74-021 and 74-031.



Defect: Some Rubber Straps may not meet the mandatory Australian safety Standard for the durability of warning labels on rubber straps, elastic luggage straps and "occy straps".

Hazard: The required yellow warning label may easily rip, tear or detach from the Rubber Strap.

What to do: Consumers should immediately stop using the Rubber Straps and inspect the label. If the yellow warning label can be easily ripped, torn or removed, the consumer should return the Rubber Straps to their place of purchase for a full refund or replacement. If the yellow warning label cannot be easily ripped, torn or removed, the Rubber Strap is compliant.

Contact details:

Joe Xuereb
RSP Automotive & Industrial Pty Ltd
Ph: (03) 9305 4000
Email: recalls@rsp.net.au
Web: www.rsp.net.au

See www.recalls.gov.au for
Australian Product Recall Information